



NOSE ASSEMBLY DATA SHEET



NOTE: Use 3/16 hex wrench in drawbolt adapter (10) to aid nose assembly removal.

5/05

GAGE BILT

GAGE BILT PRODUCTS CORP.

14500 Barber Drive (586) 771-7664
Warren, Mi 48088 (586) 771-2665 Fax
e-mail: solutions@gagebilt.com / www.gagebilt.com

Type:		Fastener:	Recommended Tool:
1/8, 5/32 & 3/16 Ø		CHERRYMAX®	GBP751B
Ref. No.	Qty.	Description	456MAX-751A-43OS
1	1	Drawbolt Saddle	78101
2	1	Dowel Pin	76302
3	1	Roll Pin	78103
4	1	Jaw	76304
5	1	Guard	76305
6	1	Spring	76306
7	1	Drawbolt	75107
8	1	Roll Pin	76308
9	1	Frame	76309
10	1	Drawbolt Adapter	70453
11	1	Frame Adapter Assembly	70460