


Avro “Tungsten” Bucking Bars


MODEL NUMBER AND SERIAL NUMBER ENGRAVED IN BLUE AREA

Tungsten Bucking Bars are not covered under warranty due to the type of material and porosity issues that occur in pressed metals.


A56001




A56002




A56003




A56004




A56005




A56006




A56007




A56008




A56009




A56010




A56011




A56014




A56015




A56018




A56021




A56022




A56023




A56025



A56026



A56027




Avro “Tungsten” Bucking Bars


MODEL NUMBER AND SERIAL NUMBER ENGRAVED IN BLUE AREA

Tungsten Bucking Bars are not covered under warranty due to the type of material and porosity issues that occur in pressed metals.


A56029




A56030




A56031




A56035




A56036




A56037




A56038




A56040




A56041




A56042




A56043




A56044




A56045




A56047




A56049




A56050




A56051




A56052



A56055



A56056




Avro Tungsten Bucking Bars


MODEL NUMBER AND SERIAL NUMBER ENGRAVED IN BLUE AREA

Tungsten Bucking Bars are not covered under warranty due to the type of material and porosity issues that occur in pressed metals.


A56058




A56059BM




A56061




A56062




A56065




A56066




A56067




A56068




A56070




A56071




A56072




A56074




A56075




A56076




A56077




A56078




A56079




A56080



A56081



A56082




Avro “Tungsten” Bucking Bars


MODEL NUMBER AND SERIAL NUMBER ENGRAVED IN BLUE AREA

Tungsten Bucking Bars are not covered under warranty due to the type of material and porosity issues that occur in pressed metals.


A56083




A56085




A56086




A56088




A56089




A56090




A56091




A56092




A56093




A56094




A56095




A56096




A56097




A56099




A56102




A56103




A56104




A56105



A56108



A56109




F


Avro “Tungsten” Bucking Bars

Tungsten Bucking Bars are not covered under warranty due to the type of material and porosity issues that occur in pressed metals.


A56109A




A56109C




A56109D




A56109E




A560109F



A560109G



A560109H



F

The Bucking Bars shown represent only some of the models available.

Should you require a specific design not shown.
Simply provide **AVROTOOLS** with your drawing and we will custom design the Bucking Bar you require